



Don't approach someone on a lift truck without attracting their attention and then wait until lift truck is stationary. Always ensure you have made eye contact and that they have seen you.



If the operator is in the middle of stacking / de-stacking – Wait. Do not try to pass behind or in front of the forklift



Don't pass between a stationary lift truck and a fixed object such as a wall / load / machine or racking until you have made eye contact with the operator and you are sure that they have seen you.



Be aware of the location of the pedestrian walkway(s) and the lift truck travelling routes. Take care when using the pedestrian walkways, treat it like a road and look in both directions if crossing a lift truck travelling route.



Do not enter the aisle or an adjoining aisle where a forklift is operating



Never assume that the forklift operator has seen you.



Always wear your high visibility vest